DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-001808 Address: 333 Burma Road **Date Inspected:** 23-Mar-2008

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1700 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Xu Le Feng, Ye Yong Jun **CWI Present:** Yes No **Inspected CWI report:** Yes No N/A **Rod Oven in Use:** Yes No N/A Yes N/A N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No Yes N/A N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A Yes No N/A **Approved Drawings:** Yes No **Approved WPS:** Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** Tower Mock-ups and OBG

Summary of Items Observed:

The Quality Assurance (QA) Inspector Gregory Bertlesman arrived on site at the Zhenhua Port Machinery Company facility on Changxing island, China to periodically monitor welding and Quality Control functions. While on site the Quality Assurance Inspector observed and/or discovered the following.

Production Monitoring Tests Macro Etches

The Quality Assurance Inspector continued to record all previous data collected from various Quality Assurance Inspectors to a new Macro Etch Log. The Data is now current and up to date. This Information was forwarded to Structures Material Representative Patrick Lowry for review.

ZPMC Quality Control Inspector Sun Wei relayed he had not performed any visual inspections to any macro etch samples this weekend. Mr. Sun relayed that all samples from the previous four days would be available for review late Monday morning.

The Quality Assurance Inspector observed ZPMC cutting various macro etch samples from the production monitoring test ribs performed over the last four days.

Summary of Conversations:

As stated in the contents of the above report.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

remedial efforts please contact Mazen Wahbeh, (818) 292-0659, who represents the Office of Structural Materials for your project.

Inspected By:	Bertlesman, Greg	Quality Assurance Inspector
Reviewed By:	Cuellar,Robert	QA Reviewer